


H-201288 1/9


REPLACEMENT SHEET






H-201288 2/9

REPLACEMENT SHEET









. <u>:</u> H-201288 4/9





H-201288 5/9







H-201288 6/9





Figure 6








FIG. 7

A Machinet And Apparation consequence and Lin Attenuation In An Optical Torque Sensor

> H-201288 8/9






Fig. 8

